Vehicle Diagnostic Report
The Report is created by **LAUNCH X-431**

Vehicle Information

Year:2020.10-

Make:Toyota

Model:Corolla HV

VIN:SB1Z53BE10E073579

Vehicle Software Version:V51.00

Diagnostic Application Version:V1.00.006

Diagnostic path:16PIN DLC(Europe and Other) > Corolla HV > MZEH12 > M20A-FXS > 2020.10- > Others

Repair Shop

Shop Name:!

Address:

Zip Code:

Telephone:

Email:

SN:988684032318

Test Time:2025-06-26 05:41:08

System fault code 【Pre-Repair】

The following systems are OK:

1.EOBD/OBD II

2.ECM (Engine Control Module)

3.HC (Hybrid Control)

4.CCS (Cruise Control)

5.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRC (Traction Control System)

6.EPB (Electrical Parking Brake)

7.SAS (Steering Angle Sensor)

8.EMPS (Electronic Motor Power Steering)

9.SRS (Supplemental Inflatable Restraint System)

10.PCS (Pre-Collision System)

11.AC (Air Conditioning)

12.TPMS (Tire Pressure Monitoring System)

13.CM (Combination Meter)

14.BCM (Body Control Module)

15.ES (Entry&Start)

16.MG (Motor Generator)

17.CGW (Central Gateway)

18.DDM (Driver Door Motor)

19.PDM (Passenger Door Motor)

20.RLDM (Rear Left Door Motor)

21.RRDM (Rear Right Door Motor)

22.MSW (Master Switch)

23.RHS (Rain and/or Humidity Sensor)

24.PSC (Power Source Control)

25.TS (Telematics System)

26.NS (Navigation System)

27.FRS (Front Radar Sensor)

28.FRC (Front Recognition Camera)

29.FRCFLC (Front Recognition Camera (Front Lighting Control))

30.LC (Lane Control)

31.RSA (Road Sign Assist)

32.CW (Clearance Warning)

33.AVAS (Acoustic Vehicle Alerting System)

· ·

Disclaimer