

# Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

## Repair Shop

Shop Name:!

Address:

Zip Code:

Telephone:

Email:

SN:988684032318

Test Time:2024-12-02 05:38:10



## Vehicle Information

Make:Mercedes-Benz

Model:253.381 - GLC 200 4MATIC Sedan

VIN:WDC2533811F731173

Odometer:40482 miles

Vehicle Software Version:V50.26

Diagnostic Application Version:V1.00.005

Diagnostic path:253>253.381 - GLC 200 4MATIC Coupe / GLC 260 4MATIC Coupe>Health Report



## System fault code

The following systems are OK:

- 1.FSCU - Fuel Pump
- 2.ECM - Engine Control Module(ME)
- 3.REAR SAM - Rear Signal Acquisition And Actuation Module
- 4.N25/17 (Front seat heater/seat ventilation control unit)
- 5.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 6.LIN: AISP - Dimming Inside Rearview Mirror
- 7.B95 (Battery sensor)
- 8.B38/2 (Rain/light sensor with additional functions)
- 9.Windshield wiper
- 10.DDW - DC/DC Converter
- 11.G1/3 (48 V on-board electrical system battery)
- 12.EZS - Electronic Ignition Lock
- 13.SG-SW-L - Left Headlamp
- 14.SG-SW-R - Right Headlamp
- 15.KG - KEYLESS GO

- 16.OCP - Overhead Control Panel
- 17.LIN: AS - Alarm Siren
- 18.SRS - Supplemental Restraint System
- 19.N110 (Weight Sensing System (WSS) control unit)
- 20.SCM - Steering Column Module
- 21.LRE - Steering Wheel Electronics
- 22.Active Brake Assist
- 23.PTS - PARKTRONIC
- 24.TPMS - Tire Pressure Monitoring System
- 25.ES - Electrical Power Steering
- 26.ESP - Electronic Stability Program
- 27.ZAN - Audio/COMAND Display
- 28.Control Unit For Telematics Services
- 29.Audio - Audio Or COMAND
- 30.IC - Instrument Cluster
- 31.TPAD - Touchpad
- 32.N72/1 (Upper control panel control unit)
- 33.N72 (Lower control panel)
- 34.N72/5 (Right lower control panel)
- 35.AC - Air Conditioning
- 36.DCU-LF - Left Front Door
- 37.DCU\_RF - Right Front Door
- 38.DCU-LR - Left Rear Door
- 39.DCU-RR - Right Rear Door
- 40.HKS - Tailgate Control