

# Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

## Repair Shop

Shop Name:!

Address:

Zip Code:

Telephone:

Email:

SN:988684032318

Test Time:2024-09-27 02:41:09



## Vehicle Information

Year:2019.05

Make:BMW

Model:318d

VIN:WBA8X11080BH26244

Odometer:76723 miles

Vehicle Software Version:V51.35

Diagnostic Application Version:V1.00.005

Diagnostic path:Health Report



## System fault code

The following systems are OK:

- 1.TCM (Transmission Control Module - EGS)
- 2.GWS (Gear Selector Switch)
- 3.ABS (Anti-Lock Braking System - DSC)
- 4.EPS (Electronic Power Steering)
- 5.SCR (Selective Catalytic Reduction)
- 6.HKFM/HKL (Automatic Luggage Compartment Lid Actuation)
- 7.LHML (LED Main Light Module, Left)
- 8.LHMR (LED Main Light Module, Right)
- 9.IC (Instrument Cluster - INSTR)
- 10.CIC (Car Information Computer)
- 11.ZBE/CON (Controller)
- 12.CAS (Car Access System - CAS/FEM/BDC)
- 13.ECM (Engine Control Module - DME/DDE)
- 14.ICM (Integrated Chassis Management)/RLM\_2L (Tail Light Module, Inner Left)
- 15.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)

16.ZGM (Central Gateway Module)

17.FZD (Function Center, Roof)

18.ECALL (Emergency Call)

19.FRM (Footwell Module)/TSGFA (Driver Door Control Unit)

20.AC (Air Conditioning - IHKA)