

# Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

## Repair Shop

Shop Name:!

Address:

Zip Code:

Telephone:

Email:

SN:988684032318

Test Time:2025-03-07 02:45:54



## Vehicle Information

Year:2021.02

Make:BMW

Model:318d

VIN:WBA5V31080FL00533

Odometer:64712 miles

Vehicle Software Version:V51.35

Diagnostic Application Version:V1.00.005

Diagnostic path:Health Report



## System fault code

The following systems are OK:

- 1.TCM (Transmission Control Module - EGS)
- 2.GWS (Gear Selector Switch)
- 3.ABS (Anti-Lock Braking System - DSC)
- 4.ICMV (Vertical Dynamics Management)/VIP (Virtual Integration System)
- 5.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 6.SZL (Switch Center, Steering Column)/BATT48 (Battery Electronics 48 V)
- 7.TRVC (All Round View Camera)
- 8.SCR (Selective Catalytic Reduction)
- 9.ZGM (Central Gateway Module)
- 10.LHML (LED Main Light Module, Left)
- 11.LHMR (LED Main Light Module, Right)
- 12.PCU48 (Power Control Unit 48 V)
- 13.ULF-SBX-H (Interface Box High)/SGE48V (Starter Motor Generator 48 V)
- 14.FZD (Function Center, Roof)
- 15.ZBE/CON (Controller)

- 16.AC (Air Conditioning - IHKA)
- 17.CAS (Car Access System - CAS/FEM/BDC)
- 18.ECM (Engine Control Module - DME/DDE)
- 19.PMA (Parking Assistant)
- 20.AMP (Amplifier)
- 21.IC (Instrument Cluster - INSTR)
- 22.ECALL (Emergency Call)
- 23.CIC (Car Information Computer)