Inspection Report

This report is created by

LAUNCH X-431

Vehicle Information

VIN: WBA51BL070W*****

Vehicle manufacturer/model: BMW/520d xDrive

Year of manufacture: 2021.03 Mileage: 37835 miles *Manual data entry Vehicle Software Version: V51.35

Inspection Organization

Name: ! Address: Contact Number: SN: 988684032318

2.LMV/VTG (Transfer Case)

10.BFS (Seat Module, Passenger)

13.CIC (Car Information Computer)

12.CAS (Car Access System - CAS/FEM/BDC)

TCM (Transmission Control Module - EGS)

Inspections are normal for Infotainment system

11.AC (Air Conditioning - IHKA)

1.AMP (Amplifier)

2.ECALL (Emergency Call)

LMV/VTG (Transfer Case)

GWS (Gear Selector Switch)

FZD (Function Center, Roof)

AMP (Amplifier)

ECALL (Emergency Call)

CIC (Car Information Computer)

Time and date of inspection: 10/03/2025 12:54:05

Inspections are normal for Power system

1.TCM (Transmission Control Module - EGS)



Normal

Normal

Normal ~

Normal

Inspection Result

3.GWS (Gear Selector Switch) 4.SCR (Selective Catalytic Reduction) 5.ECM (Engine Control Module - DME/DDE) Inspections are normal for Chassis system 1.ICMV (Vertical Dynamics Management)/VIP (Virtual Integration System) Inspections are normal for Safety and Security system 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM) 2.SZL (Switch Center, Steering Column)/BATT48 (Battery Electronics 48 V) 3.TRSVC (All Round View Camera) 4.PMA (Parking Assistant) 5.ABS (Anti-Lock Braking System - DSC) Inspections are normal for Vehicle body system 1.ZGM (Central Gateway Module) 2.LHML (LED Main Light Module, Left) 3.LHMR (LED Main Light Module, Right) 4.PCU48 (Power Control Unit 48 V) 5.ULF-SBX-H (Interface Box High)/SGE48V (Starter Motor Generator 48 V) 6.FZD (Function Center, Roof) 7.IC (Instrument Cluster - INSTR) 8.ZBE/CON (Controller) 9.FAS (Seat Module, Driver)

Professional Report

ICMV (Vertical Dynamics Management)/VIP (Virtual Integration System)	Normal V
SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)	Normal ∨
SZL (Switch Center, Steering Column)/BATT48 (Battery Electronics 48 V)	Normal ∨
TRSVC (All Round View Camera)	Normal ∨
SCR (Selective Catalytic Reduction)	Normal ∨
ZGM (Central Gateway Module)	Normal ∨
PMA (Parking Assistant)	Normal ∨
LHML (LED Main Light Module, Left)	Normal ~
LHMR (LED Main Light Module, Right)	Normal V
PCU48 (Power Control Unit 48 V)	Normal ∨
ULF-SBX-H (Interface Box High)/SGE48V (Starter Motor Generator 48 V)	Normal V

IC (Instrument Cluster - INSTR) Normal V ZBE/CON (Controller) Normal

Normal FAS (Seat Module, Driver) BFS (Seat Module, Passenger) Normal ~

AC (Air Conditioning - IHKA) Normal ~ CAS (Car Access System - CAS/FEM/BDC) Normal

ECM (Engine Control Module - DME/DDE) Normal ~

ABS (Anti-Lock Braking System - DSC) Normal Normal

Normal >

Normal ~

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.