

# Inspection Report

This report is created by



## Vehicle Information

VIN: WVVZZZ3CZME\*\*\*\*\*  
Vehicle manufacturer/model: VW/  
Year of manufacture: 2021  
Mileage: 59955 miles  
Vehicle Software Version: V29.00

## Inspection Organization

Name: !  
Address:  
Contact Number: ☎  
SN: 988684032318  
Time and date of inspection: 10/24/2025 13:20:42



## Inspection Result

Inspections are normal for Power system

1.01 Engine Electronics

Inspections are normal for Safety and Security system

- 1.03 Brake Electronics
- 2.13 Distance Regulation
- 3.15 Airbag
- 4.23 Brake Boost
- 5.2B Steering Column Lock
- 6.44 Power Steering
- 7.76 Parking Aid
- 8.A5 Front Sensor For Drivers Assistant Systems

Inspections are normal for Vehicle body system

- 1.08 Climate Control Module
- 2.09 Electronic Central Electric
- 3.17 Instrument Cluster
- 4.19 Data Bus OBD Interface
- 5.42 Driver's Door Electronics
- 6.52 Passenger's Door Electronics
- 7.5F Information Electronics 1
- 8.B7 Interface For Access/Start System

Inspections are normal for Infotainment system

- 1.75 Emergency Call Module And Communication Unit

## Professional Report

|                                                 |        |
|-------------------------------------------------|--------|
| 01 Engine Electronics                           | Normal |
| 03 Brake Electronics                            | Normal |
| 08 Climate Control Module                       | Normal |
| 09 Electronic Central Electric                  | Normal |
| 13 Distance Regulation                          | Normal |
| 15 Airbag                                       | Normal |
| 17 Instrument Cluster                           | Normal |
| 19 Data Bus OBD Interface                       | Normal |
| 23 Brake Boost                                  | Normal |
| 2B Steering Column Lock                         | Normal |
| 42 Driver's Door Electronics                    | Normal |
| 44 Power Steering                               | Normal |
| 52 Passenger's Door Electronics                 | Normal |
| 5F Information Electronics 1                    | Normal |
| 75 Emergency Call Module And Communication Unit | Normal |
| 76 Parking Aid                                  | Normal |
| A5 Front Sensor For Drivers Assistant Systems   | Normal |
| B7 Interface For Access/Start System            | Normal |

## Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.