

Inspection Report

This report is created by



Vehicle Information

VIN: WBAJY41050C*****
 Vehicle manufacturer/model: BMW/630d xDrive
 Year of manufacture: 2022.05
 Mileage: 43455 miles
 Vehicle Software Version: V51.35

Inspection Organization

Name: !
 Address:
 Contact Number: ☐
 SN: 988684032318
 Time and date of inspection: 04/29/2026 08:33:04



Inspection Result

There are 1 issues for Vehicle body system:
1.Radio Remote Control: Battery Undervoltage

Inspections are normal for Power system

- TCM (Transmission Control Module - EGS)
- GWS (Gear Selector Switch)
- SCR (Selective Catalytic Reduction)
- ECM (Engine Control Module - DME/DDE)
- LMV/VTG (Transfer Case)

Inspections are normal for Chassis system

- ICMV (Vertical Dynamics Management)/VIP (Virtual Integration System)
- VDC/VDM (Vertical Dynamics Management)

Inspections are normal for Safety and Security system

- EPB (Electrical Parking Brake - EMF)/SRR_HL (Rear Radar Sensor Near Range Left)
- HSR (Rear-Axle Slip-Angle Control)
- EPS (Electronic Power Steering)
- SZL (Switch Center, Steering Column)/BATT48 (Battery Electronics 48 V)
- TRSVC (All Round View Camera)
- HC/SWW (Lane Change Warning)/SRR_HR (Rear Radar Sensor Near Range Right)
- ABS (Anti-Lock Braking System - DSC)
- SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- PMA (Parking Assistant)
- KAFAS (Camera Based Driver Assist Systems)

Inspections are normal for Vehicle body system

- HKFM/HKL (Automatic Luggage Compartment Lid Actuation)
- ZGM (Central Gateway Module)
- LHMR (LED Main Light Module, Right)
- PCU48 (Power Control Unit 48 V)
- ULF-SBX-H (Interface Box High)/SGE48V (Starter Motor Generator 48 V)
- IC (Instrument Cluster - INSTR)
- ZBE/CON (Controller)
- LHML (LED Main Light Module, Left)
- FZD (Function Center, Roof)
- CIC (Car Information Computer)
- FAS (Seat Module, Driver)
- BFS (Seat Module, Passenger)
- AHM (Trailer Module)
- AC (Air Conditioning - IHKA)

Inspections are normal for Infotainment system

- AMP (Amplifier)
- ECALL (Emergency Call)

Professional Report

TCM (Transmission Control Module - EGS)	Normal
GWS (Gear Selector Switch)	Normal
EPB (Electrical Parking Brake - EMF)/SRR_HL (Rear Radar Sensor Near Range Left)	Normal
HSR (Rear-Axle Slip-Angle Control)	Normal
EPS (Electronic Power Steering)	Normal
ICMV (Vertical Dynamics Management)/VIP (Virtual Integration System)	Normal
SZL (Switch Center, Steering Column)/BATT48 (Battery Electronics 48 V)	Normal
TRSVC (All Round View Camera)	Normal
HC/SWW (Lane Change Warning)/SRR_HR (Rear Radar Sensor Near Range Right)	Normal
SCR (Selective Catalytic Reduction)	Normal
HKFM/HKL (Automatic Luggage Compartment Lid Actuation)	Normal
ZGM (Central Gateway Module)	Normal
LHMR (LED Main Light Module, Right)	Normal
PCU48 (Power Control Unit 48 V)	Normal
ULF-SBX-H (Interface Box High)/SGE48V (Starter Motor Generator 48 V)	Normal
IC (Instrument Cluster - INSTR)	Normal
ZBE/CON (Controller)	Normal
VDC/VDM (Vertical Dynamics Management)	Normal
ECM (Engine Control Module - DME/DDE)	Normal
LMV/VTG (Transfer Case)	Normal
ABS (Anti-Lock Braking System - DSC)	Normal
SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)	Normal
PMA (Parking Assistant)	Normal
AMP (Amplifier)	Normal
LHML (LED Main Light Module, Left)	Normal
FZD (Function Center, Roof)	Normal
KAFAS (Camera Based Driver Assist Systems)	Normal
ECALL (Emergency Call)	Normal
CIC (Car Information Computer)	Normal
FAS (Seat Module, Driver)	Normal
BFS (Seat Module, Passenger)	Normal
AHM (Trailer Module)	Normal
AC (Air Conditioning - IHKA)	Normal
CAS (Car Access System - CAS/FEM/BDC)	Abnormal 1

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.