

Inspection Report

This report is created by



Vehicle Information

VIN: W1N2476881W*****

Vehicle manufacturer/model: Mercedes-Benz/247.688 - GLB 200 4MATIC

Year of manufacture:

Mileage: 38434 miles

Vehicle Software Version: V50.26

Inspection Organization

Name: I

Address:

Contact Number: ☎

SN: 988684032318

Time and date of inspection: 05/23/2026 12:57:00



Inspection Result

Inspections are normal for Power system

- 1.PTCU - Drivetrain
- 2.ME - Motor Electronics
- 3.TCM - Transmission Control Module

Inspections are normal for Chassis system

- 1.TPM - Tire Pressure Monitor

Inspections are normal for Safety and Security system

- 1.SRS - Supplemental Restraint System
- 2.SCM - Steering Column Module
- 3.PTS - PARKTRONIC
- 4.ES - Electrical Power Steering
- 5.ESP - Electronic Stability Program

Inspections are normal for Vehicle body system

- 1.VG - All - Wheel Drive
- 2.FSCU - Fuel Pump
- 3.AML - Ambiance Light
- 4.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 5.LIN: AISP - Dimming Inside Rearview Mirror
- 6.B95 (Battery sensor)
- 7.N70 (Overhead control panel control unit)
- 8.N25/17 (Front seat heater/seat ventilation control unit)
- 9.LIN: RGLS - Rain/Light Sensor
- 10.Windshield wiper
- 11.EZS - Electronic Ignition Lock
- 12.SG-SW-L - Left Headlamp
- 13.SG-SW-R - Right Headlamp
- 14.N110 (Weight Sensing System (WSS) control unit)
- 15.SD - Sliding Roof/Panoramic Sliding Sunroof
- 16.LRE - Steering Wheel Electronics
- 17.ATA - Interior Motion Sensor
- 18.LIN: AS - Alarm Siren
- 19.MFK - Multifunction Camera
- 20.Control Unit For Telematics Services
- 21.IC - Instrument Cluster
- 22.AAC - Air Conditioning
- 23.DCU-LF - Left Front Door
- 24.N69/3 (Left rear door control unit)
- 25.DCU-RF - Right Front Door
- 26.N69/4 (Right rear door control unit)

Inspections are normal for Infotainment system

- 1.ZAN - Audio/COMAND Display
- 2.Audio - Audio Or COMAND
- 3.TPAD - Touchpad

Professional Report

| | |
|--|--------|
| VG - All - Wheel Drive | Normal |
| PTCU - Drivetrain | Normal |
| ME - Motor Electronics | Normal |
| FSCU - Fuel Pump | Normal |
| TCM - Transmission Control Module | Normal |
| AML - Ambiance Light | Normal |
| Driver-side SAM - Front Signal Acquisition And Actuation Module | Normal |
| LIN: AISP - Dimming Inside Rearview Mirror | Normal |
| B95 (Battery sensor) | Normal |
| N70 (Overhead control panel control unit) | Normal |
| N25/17 (Front seat heater/seat ventilation control unit) | Normal |
| LIN: RGLS - Rain/Light Sensor | Normal |
| Windshield wiper | Normal |
| EZS - Electronic Ignition Lock | Normal |
| SG-SW-L - Left Headlamp | Normal |
| SG-SW-R - Right Headlamp | Normal |
| SRS - Supplemental Restraint System | Normal |
| N110 (Weight Sensing System (WSS) control unit) | Normal |
| SCM - Steering Column Module | Normal |
| SD - Sliding Roof/Panoramic Sliding Sunroof | Normal |
| LRE - Steering Wheel Electronics | Normal |
| ATA - Interior Motion Sensor | Normal |
| LIN: AS - Alarm Siren | Normal |
| PTS - PARKTRONIC | Normal |
| MFK - Multifunction Camera | Normal |
| TPM - Tire Pressure Monitor | Normal |
| ES - Electrical Power Steering | Normal |
| ESP - Electronic Stability Program | Normal |
| ZAN - Audio/COMAND Display | Normal |
| Control Unit For Telematics Services | Normal |
| Audio - Audio Or COMAND | Normal |
| IC - Instrument Cluster | Normal |
| TPAD - Touchpad | Normal |
| AAC - Air Conditioning | Normal |
| DCU-LF - Left Front Door | Normal |
| N69/3 (Left rear door control unit) | Normal |
| DCU-RF - Right Front Door | Normal |
| N69/4 (Right rear door control unit) | Normal |

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.