

## Inspection Report

This report is created by



### Vehicle Information

VIN: W1K5J8HB3PN\*\*\*\*\*

Vehicle manufacturer/model: Mercedes-Benz/118.387 - CLA 200 Coupe

Year of manufacture:

Mileage: 36180 miles

Vehicle Software Version: V50.26

### Inspection Organization

Name: !

Address:

Contact Number: ☐

SN: 988684032318

Time and date of inspection: 06/10/2026 08:33:30



### Inspection Result

#### Inspections are normal for Power system

- 1.PTCU - Drivetrain
- 2.ME - Motor Electronics
- 3.TCM - Transmission Control Module

#### Inspections are normal for Chassis system

- 1.TPM - Tire Pressure Monitor

#### Inspections are normal for Safety and Security system

- 1.SRS - Supplemental Restraint System
- 2.SCM - Steering Column Module
- 3.PTS - PARKTRONIC
- 4.ES - Electrical Power Steering
- 5.ESP - Electronic Stability Program

#### Inspections are normal for Vehicle body system

- 1.FSCU - Fuel Pump
- 2.AML - Ambiance Light
- 3.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 4.B95 (Battery sensor)
- 5.N70 (Overhead control panel control unit)
- 6.N25/17 (Front seat heater/seat ventilation control unit)
- 7.LIN: RGLS - Rain/Light Sensor
- 8.Windshield wiper
- 9.EZS - Electronic Ignition Lock
- 10.SG-SW-L - Left Headlamp
- 11.SG-SW-R - Right Headlamp
- 12.N110 (Weight Sensing System (WSS) control unit)
- 13.LRE - Steering Wheel Electronics
- 14.ATA - Interior Motion Sensor
- 15.LIN: AS - Alarm Siren
- 16.Active Brake Assist
- 17.MFK - Multifunction Camera
- 18.Control Unit For Telematics Services
- 19.IC - Instrument Cluster
- 20.AAC - Air Conditioning
- 21.DCU-LF - Left Front Door
- 22.N69/3 (Left rear door control unit)
- 23.DCU-RF - Right Front Door
- 24.N69/4 (Right rear door control unit)

#### Inspections are normal for Infotainment system

- 1.ZAN - Audio/COMAND Display
- 2.Audio - Audio Or COMAND
- 3.TPAD - Touchpad

### Professional Report

PTCU - Drivetrain	Normal
ME - Motor Electronics	Normal
FSCU - Fuel Pump	Normal
TCM - Transmission Control Module	Normal
AML - Ambiance Light	Normal
Driver-side SAM - Front Signal Acquisition And Actuation Module	Normal
B95 (Battery sensor)	Normal
N70 (Overhead control panel control unit)	Normal
N25/17 (Front seat heater/seat ventilation control unit)	Normal
LIN: RGLS - Rain/Light Sensor	Normal
Windshield wiper	Normal
EZS - Electronic Ignition Lock	Normal
SG-SW-L - Left Headlamp	Normal
SG-SW-R - Right Headlamp	Normal
SRS - Supplemental Restraint System	Normal
N110 (Weight Sensing System (WSS) control unit)	Normal
SCM - Steering Column Module	Normal
LRE - Steering Wheel Electronics	Normal
ATA - Interior Motion Sensor	Normal
LIN: AS - Alarm Siren	Normal
Active Brake Assist	Normal
PTS - PARKTRONIC	Normal
MFK - Multifunction Camera	Normal
TPM - Tire Pressure Monitor	Normal
ES - Electrical Power Steering	Normal
ESP - Electronic Stability Program	Normal
ZAN - Audio/COMAND Display	Normal
Control Unit For Telematics Services	Normal
Audio - Audio Or COMAND	Normal
IC - Instrument Cluster	Normal
TPAD - Touchpad	Normal
AAC - Air Conditioning	Normal
DCU-LF - Left Front Door	Normal
N69/3 (Left rear door control unit)	Normal
DCU-RF - Right Front Door	Normal
N69/4 (Right rear door control unit)	Normal

### Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.