

Inspection Report

This report is created by



Vehicle Information

VIN: YV1UZK5VXP1*****
Vehicle manufacturer/model: Volvo/XC60 (18-)
Year of manufacture: 2023
Mileage: 35949 miles
Vehicle Software Version: V45.00

Inspection Organization

Name: !
Address:
Contact Number:
SN: 988684032318
Time and date of inspection: 07/06/2026 14:40:07



Inspection Result

Inspections are normal for Power system

- 1.TCM (Transmission Control Module)
- 2.DIESEL ENG (Fuel System/Combined System)
- 3.DEM (Differential Electronic Module)
- 4.EGSM (Electronic Gear Selector Module)
- 5.NRCM (NOx Reduction Control Module)

Inspections are normal for Safety and Security system

- 1.ABS (Anti-Lock Braking System)
- 2.SRS (Supplemental Inflatable Restraint System)
- 3.SAS (Steering Wheel Angle Sensor Module)
- 4.PAC (Parking Assistance Camera)
- 5.PSCM (Power Steering Control Module)
- 6.BMS (Battery Monitoring System)
- 7.IMS (Interior Motion Sensor)
- 8.BBS (Battery Backed-Up Sounder)
- 9.HCML (Headlight Control Module Left)
- 10.HCMR (Headlight Control Module Right)

Inspections are normal for Vehicle body system

- 1.ABS 2 (Anti-Lock Brake System 2)
- 2.VCU 1 (Vehicle Computational Unit 1)
- 3.MVBM (Middle Voltage Battery Module)
- 4.TCAM (Tbox Control Unit And Antenna Module)
- 5.VGM (Vehicle Gateway Module)
- 6.MVCM (Middle Voltage Converter Module)
- 7.CEM (Central Electrical Module)
- 8.DIM (Driver Information Module)
- 9.PDM (Passenger Door Module)
- 10.DDM (Driver Door Module)
- 11.CCM (Climate Control Module)
- 12.SWM (Steering Wheel Module)
- 13.POT (Power Operated Tailgate Module)
- 14.ISGM (Integrated Starter Engine Module)
- 15.ASDM (Active Safety Domain Master)
- 16.FLC2 (Front Land Camera 2)
- 17.FLR (Forward Looking Radar)

Inspections are normal for Infotainment system

- 1.AUD (Audio Module)
- 2.IHU (Infotainment Head Unit)
- 3.OHC (Over Head Console)
- 4.CCD (Center Console Display)
- 5.WPC (Wireless Phone Charger)

Professional Report

TCM (Transmission Control Module)	Normal	▼
ABS (Anti-Lock Braking System)	Normal	▼
SRS (Supplemental Inflatable Restraint System)	Normal	▼
ABS 2 (Anti-Lock Brake System 2)	Normal	▼
VCU 1 (Vehicle Computational Unit 1)	Normal	▼
MVBM (Middle Voltage Battery Module)	Normal	▼
TCAM (Tbox Control Unit And Antenna Module)	Normal	▼
VGM (Vehicle Gateway Module)	Normal	▼
MVCM (Middle Voltage Converter Module)	Normal	▼
DIESEL ENG (Fuel System/Combined System)	Normal	▼
CEM (Central Electrical Module)	Normal	▼
DIM (Driver Information Module)	Normal	▼
PDM (Passenger Door Module)	Normal	▼
DDM (Driver Door Module)	Normal	▼
CCM (Climate Control Module)	Normal	▼
SWM (Steering Wheel Module)	Normal	▼
AUD (Audio Module)	Normal	▼
DEM (Differential Electronic Module)	Normal	▼
SAS (Steering Wheel Angle Sensor Module)	Normal	▼
POT (Power Operated Tailgate Module)	Normal	▼
ISGM (Integrated Starter Engine Module)	Normal	▼
PAC (Parking Assistance Camera)	Normal	▼
PSCM (Power Steering Control Module)	Normal	▼
ASDM (Active Safety Domain Master)	Normal	▼
EGSM (Electronic Gear Selector Module)	Normal	▼
IHU (Infotainment Head Unit)	Normal	▼
OHC (Over Head Console)	Normal	▼
CCD (Center Console Display)	Normal	▼
BMS (Battery Monitoring System)	Normal	▼
IMS (Interior Motion Sensor)	Normal	▼
BBS (Battery Backed-Up Sounder)	Normal	▼
NRCM (NOx Reduction Control Module)	Normal	▼
WPC (Wireless Phone Charger)	Normal	▼
HCML (Headlight Control Module Left)	Normal	▼
HCMR (Headlight Control Module Right)	Normal	▼
FLC2 (Front Land Camera 2)	Normal	▼
FLR (Forward Looking Radar)	Normal	▼

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.