

Inspection Report

This report is created by



Vehicle Information

VIN: WAUZZZFY2M2*****
Vehicle manufacturer/model: Audi/
Year of manufacture: 2021
Mileage: 59835 miles
Vehicle Software Version: V29.02

Inspection Organization

Name: !
Address:
Contact Number:
SN: 988684032318
Time and date of inspection: 07/23/2026 14:16:47



Inspection Result

Inspections are normal for Power system

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.22 All-Wheel Drive Electronics
- 4.80 Battery Control Additional Memory 1
- 5.81 Selector Lever
- 6.AC Reducing Agent Metering System

Inspections are normal for Safety and Security system

- 1.03 Brake Electronics
- 2.15 Airbag
- 3.16 Steering Column Electronics Systems
- 4.44 Power Steering
- 5.6C Rear View Camera System
- 6.A5 Front Sensor For Drivers Assistant Systems

Inspections are normal for Vehicle body system

- 1.08 Climate Control Module
- 2.09 Electronic Central Electric
- 3.17 Instrument Cluster
- 4.19 Data Bus OBD Interface
- 5.42 Driver's Door Electronics
- 6.46 Comfort System Central Control Module
- 7.52 Passenger's Door Electronics
- 8.5F Information Electronics 1
- 9.6D Rear Lid Electronics
- 10.BB Rear Drivers Side Door Electronics
- 11.BC Rear Passenger Side Door Electronics
- 12.D6 Light Control Left 2
- 13.D7 Light Control Right 2

Inspections are normal for Infotainment system

- 1.75 Emergency Call Module And Communication Unit

Professional Report

01 Engine Electronics	Normal	▼
02 Transmission Electronics	Normal	▼
03 Brake Electronics	Normal	▼
08 Climate Control Module	Normal	▼
09 Electronic Central Electric	Normal	▼
15 Airbag	Normal	▼
16 Steering Column Electronics Systems	Normal	▼
17 Instrument Cluster	Normal	▼
19 Data Bus OBD Interface	Normal	▼
22 All-Wheel Drive Electronics	Normal	▼
42 Driver's Door Electronics	Normal	▼
44 Power Steering	Normal	▼
46 Comfort System Central Control Module	Normal	▼
52 Passenger's Door Electronics	Normal	▼
5F Information Electronics 1	Normal	▼
6C Rear View Camera System	Normal	▼
6D Rear Lid Electronics	Normal	▼
75 Emergency Call Module And Communication Unit	Normal	▼
80 Battery Control Additional Memory 1	Normal	▼
81 Selector Lever	Normal	▼
A5 Front Sensor For Drivers Assistant Systems	Normal	▼
AC Reducing Agent Metering System	Normal	▼
BB Rear Drivers Side Door Electronics	Normal	▼
BC Rear Passenger Side Door Electronics	Normal	▼
D6 Light Control Left 2	Normal	▼
D7 Light Control Right 2	Normal	▼

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.