

## Inspection Report

This report is created by



### Vehicle Information

VIN: WAUZZZF29PN\*\*\*\*\*  
Vehicle manufacturer/model: Audi/  
Year of manufacture: 2023  
Mileage: 19414 miles  
Vehicle Software Version: V29.02

### Inspection Organization

Name: !  
Address:  
Contact Number: ☎  
SN: 988684032318  
Time and date of inspection: 09/05/2026 14:13:55



### Inspection Result

#### Inspections are normal for Power system

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.22 All-Wheel Drive Electronics
- 4.80 Battery Control Additional Memory 1
- 5.81 Selector Lever
- 6.AC Reducing Agent Metering System

#### Inspections are normal for Safety and Security system

- 1.03 Brake Electronics
- 2.15 Airbag
- 3.16 Steering Column Electronics Systems
- 4.3C Lane Change Assistance
- 5.44 Power Steering
- 6.6C Rear View Camera System
- 7.A5 Front Sensor For Drivers Assistant Systems
- 8.CF Lane Change Assistant 2

#### Inspections are normal for Vehicle body system

- 1.09 Electronic Central Electric
- 2.17 Instrument Cluster
- 3.19 Data Bus OBD Interface
- 4.36 Seat Adjustment, Driver Side
- 5.42 Driver's Door Electronics
- 6.46 Comfort System Central Control Module
- 7.52 Passenger's Door Electronics
- 8.5F Information Electronics 1
- 9.6D Rear Lid Electronics
- 10.BB Rear Drivers Side Door Electronics
- 11.BC Rear Passenger Side Door Electronics
- 12.D6 Light Control Left 2
- 13.D7 Light Control Right 2

#### Inspections are normal for Infotainment system

- 1.75 Emergency Call Module And Communication Unit

### Professional Report

|                                                 |        |
|-------------------------------------------------|--------|
| 01 Engine Electronics                           | Normal |
| 02 Transmission Electronics                     | Normal |
| 03 Brake Electronics                            | Normal |
| 09 Electronic Central Electric                  | Normal |
| 15 Airbag                                       | Normal |
| 16 Steering Column Electronics Systems          | Normal |
| 17 Instrument Cluster                           | Normal |
| 19 Data Bus OBD Interface                       | Normal |
| 22 All-Wheel Drive Electronics                  | Normal |
| 36 Seat Adjustment, Driver Side                 | Normal |
| 3C Lane Change Assistance                       | Normal |
| 42 Driver's Door Electronics                    | Normal |
| 44 Power Steering                               | Normal |
| 46 Comfort System Central Control Module        | Normal |
| 52 Passenger's Door Electronics                 | Normal |
| 5F Information Electronics 1                    | Normal |
| 6C Rear View Camera System                      | Normal |
| 6D Rear Lid Electronics                         | Normal |
| 75 Emergency Call Module And Communication Unit | Normal |
| 80 Battery Control Additional Memory 1          | Normal |
| 81 Selector Lever                               | Normal |
| A5 Front Sensor For Drivers Assistant Systems   | Normal |
| AC Reducing Agent Metering System               | Normal |
| BB Rear Drivers Side Door Electronics           | Normal |
| BC Rear Passenger Side Door Electronics         | Normal |
| CF Lane Change Assistant 2                      | Normal |
| D6 Light Control Left 2                         | Normal |
| D7 Light Control Right 2                        | Normal |

### Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.